

## PRICE LIST FOR REPAIRS WITH COSTS VALID FROM 04/2025 Prices include VAT

REPAIR TYPE	Price
Buckle	18.15€
Cord	18.15€
Padding on the back	25.41 €
Hole (colour differences may arise) *	25.41 €
Fabric damage between wheels	60.50€
Velcro (black if colour not available)	18.15€
Replacement of a soft handle (webbing)	18.15€
Replacement of a reinforced handle	25.41 €
Replacement of the inner lining for handbags	29.04€
Replacement of the inner lining for rucksacks	38.72€
Replacement of the inner lining for trolleys	50.82€
Replacement shoulder strap	25.41 €
Belt	18.15€
Lock / TSA Lock	24.20€
Seams	18.15€
Pushbutton	18.15€
Pulling system	38.72€
1 Wheel	24.20€
2 Wheels	30.25€
3 Wheels	36.30€
4 Wheels	42.35€
Main zipper rucksacks / briefcases	31.46 €
Main zipper handbags	25.41 €
Main zipper travel bags	38.72 €
Main zipper trolleys / sleeping bags	43.56€
Zippers for wallets, (school) accessories	25.41€
Zip pull	18.15€
Studs	18.15€
Rivet	18.15€

<sup>\*</sup> The total cost of repair is estimated after evalution of the product. We will do our utmost to repair non-warranty products to their original form as well as possible. Sometimes it is only possible to add extra seams or to use materials with a slight colour difference compared to the original colour of the product. In many cases we can only repair with a contrasting colour such as black or grey. We do not replace complete panels.