

PRICE LIST FOR REPAIRS WITH COSTS VALID FROM 2023 PRICES IN EUR WITHOUT VAT

REPAIR TYPE	PRICE
Base strengthening	19 € + VAT
Buckle	12 € + VAT
Cord	10 € + VAT
Padding on the back	16.50 € + VAT
Hole (colour differences may arise) *	16.50 € + VAT
Velcro (black if colour not available)	12 € + VAT
Replacement of a soft handle (webbing)	13 € + VAT
Replacement of a reinforced handle	19 € + VAT
Replacement of the inner lining for handbags	17 € + VAT
Replacement of the inner lining for rucksacks	18.50 € + VAT
Replacement of the inner lining for trolleys	22 € + VAT
Replacement shoulder strap	16 € + VAT
Belt	6 € + VAT
Lock / TSA Lock	16 € + VAT
Seams	12 € + VAT
Pushbutton	12 € + VAT
Seam on the shoulder strap	12 € + VAT
Pulling system	22 € + VAT
1 Wheel	15 € + VAT
2 Wheels	22 € + VAT
Main zipper rucksacks / briefcases	22 € + VAT
Main zipper handbags	17 € + VAT
Main zipper travel bags	22 € + VAT
Main zipper trolleys / sleeping bags	30 € + VAT
Additional zippers	15 € + VAT
Zippers for wallets, (school) accessories	17 € + VAT
Zip pull	10 € + VAT
Studs	11 € + VAT
Rivet	11 € + VAT
Umbrella	12 € + VAT

^{*} The total cost of repair is estimated after evaluation of the product.

We will do our utmost to repair non-warranty products to their original form as well as possible.

Sometimes it is only possible to add extra seams or to use materials with a slight colour difference compared to the original colour of the product. In many cases we can only repair with a contrasting colour such as black or grey. We do not replace complete panels.