



PRICE LIST FOR REPAIRS WITH COSTS VALID FROM 2023

Prices include VAT

| REPAIR TYPE | PRICE |
|---|---------|
| Base strengthening | 23.37 € |
| Buckle | 14.76 € |
| Cord | 12.30 € |
| Padding on the back | 20.30 € |
| Opening (colour differences may arise) * | 20.30 € |
| Velcro (black if colour not available) | 14.76 € |
| Replacement of a soft handle (webbing) | 15.99 € |
| Replacement of a reinforced handle | 23.37 € |
| Replacement of the inner lining for handbags | 20.91 € |
| Replacement of the inner lining for rucksacks | 22.76 € |
| Replacement of the inner lining for trolleys | 27.06 € |
| Replacement shoulder strap | 19.68 € |
| Belt | 7.38 € |
| Lock / TSA Lock | 19.68 € |
| Seams | 14.76 € |
| Pushbutton | 14.76 € |
| Seam on the shoulder strap | 14.76 € |
| Pulling system | 27.06 € |
| 1 Wheel | 18.45 € |
| 2 Wheels | 27.06 € |
| Main zipper rucksacks / briefcases | 27.06 € |
| Main zipper handbags | 20.91 € |
| Main zipper travel bags | 27.06 € |
| Main zipper trolleys / sleeping bags | 36.90 € |
| Additional zippers | 18.45 € |
| Zippers for wallets, (school) accessories | 20.91 € |
| Zip pull | 12.30 € |
| Studs | 13.53 € |
| Rivet | 13.53 € |
| Umbrella | 14.76 € |

*** The total cost of repair is estimated after evaluation of the product.**

*** We will do our utmost to repair non-warranty products to their original form as well as possible.**

Sometimes it is only possible to add extra seams or to use materials with a slight colour difference compared to the original colour of the product. In many cases we can only repair with a contrasting colour such as black or grey. We do not replace complete panels.