

PRICE LIST FOR REPAIRS WITH COSTS VALID FROM 04/2025 Prices include VAT

REPAIR TYPE	PRICE
Buckle	18.45€
Cord	18.45€
Padding on the back	25.83 €
Hole (colour differences may arise) *	25.83 €
Fabric damage between wheels	61.50€
Velcro (black if colour not available)	18.45€
Replacement of a soft handle (webbing)	18.45€
Replacement of a reinforced handle	25.83€
Replacement of the inner lining for handbags	29.52€
Replacement of the inner lining for rucksacks	39.36€
Replacement of the inner lining for trolleys	51.66€
Replacement shoulder strap	25.83€
Belt	18.45€
Lock / TSA Lock	24.60€
Seams	18.45€
Pushbutton	18.45€
Pulling system	39.36€
1 Wheel	24.60€
2 Wheels	30.75€
3 Wheels	36.90€
4 Wheels	43.05€
Main zipper rucksacks / briefcases	31.98€
Main zipper handbags	25.83€
Main zipper travel bags	39.36€
Main zipper trolleys / sleeping bags	44.28€
Zippers for wallets, (school) accessories	25.83€
Zip pull	18.45€
Studs	18.45€
Rivet	18.45€

^{*} The total cost of repair is estimated after evalution of the product.

^{*} We will do our utmost to repair non-warranty products to their original form as well as possible.

Sometimes it is only possible to add extra seams or to use materials with a slight colour difference compared to the original colour of the product. In many cases we can only repair with a contrasting colour such as black or grey. We do not replace complete panels.