

PRICE LIST FOR REPAIRS WITH COSTS VALID FROM 2023 Prices include VAT

| REPAIR TYPE | PRICE |
|---|--------|
| Base strengthening | £19.00 |
| Buckle | £12.00 |
| Cord | £10.00 |
| Padding on the back | £16.50 |
| Opening (colour differences may arise)* | £16.50 |
| Velcro (black if colour not available) | £12.00 |
| Replacement of a soft handle (webbing) | £13.00 |
| Replacement of a reinforced handle | £19.00 |
| Replacement of the inner lining for handbags | £17.00 |
| Replacement of the inner lining for rucksacks | £18.50 |
| Replacement of the inner lining for trolleys | £22.00 |
| Replacement shoulder strap | £16.00 |
| Belt | £6.00 |
| Lock / TSA Lock | £16.00 |
| Seams | £12.00 |
| Pushbutton | £12.00 |
| Seam on the shoulder strap | £12.00 |
| Pulling system | £22.00 |
| 1 Wheel | £15.00 |
| 2 Wheels | £22.00 |
| Main zipper rucksacks / briefcases | £22.00 |
| Main zipper handbags | £17.00 |
| Main zipper travel bags | £22.00 |
| Main zipper trolleys / sleeping bags | £30.00 |
| Additional zippers | £13.00 |
| Zippers for wallets, (school) accessories | £17.00 |
| Zip pull | £10.00 |
| Studs | £11.00 |
| Rivet | £11.00 |
| Umbrella | £12.00 |

^{*} The total cost of repair is estimated after evalution of the product.

We will do our utmost to repair non-warranty products to their original form as well as possible. Sometimes it is only possible to add extra seams or to use materials with a slight colour difference compared to the original colour of the product. In many cases we can only repair with a contrasting colour such as black or grey. We do not replace complete panels.